

PERFORMANCE DATA OF U.S. NAVAL OBSERVATORY
VLG-11 HYDROGEN MASERS SINCE SEPTEMBER 1983

R.F.C. Vessot, E.M. Mattison, E.A. Imbier and Z.C. Zhai

Smithsonian Astrophysical Observatory

Cambridge, Massachusetts 02138

W.J. Klepczynski, P.G. Wheeler, A.J. Kubik, and G.M.R. Winkler

U.S. Naval Observatory, Washington, D.C. 20390

In 1983, two VLG-11 masers were delivered to the U.S. Naval Observatory by the Smithsonian Astrophysical Observatory. Last year the short-term stability of these masers was reported and the effect of this short-term stability on timekeeping performance was discussed by G.M.R. Winkler. [1] Since the date of installation, 13 September 1983, data on the masers' long-term performance have been accumulated. Figure 1 from reference [1] shows the Allan variance, $\sigma(\tau)$, of the relative frequency between the masers. This variance reaches a minimum of about 4 parts in 10^{16} at averaging times of 5×10^3 seconds and rises at longer averaging times due, at least partly, to systematic frequency drift.

In this paper we discuss the systematic frequency drifts, expressed as $\frac{1}{f} \frac{df}{dt}$ and given in units of fractional frequency difference per day.

Figure 2 is a plot of $\frac{1}{f} \frac{df}{dt}$ in units of 10^{-15} per day versus calendar day starting in September of 1983 and continuing through October of 1984. Table 1 is a chronology of activity involving SAO VLG-11 masers P18 and P19.

Report Documentation Page				Form Approved OMB No. 0704-0188	
Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.					
1. REPORT DATE NOV 1984		2. REPORT TYPE		3. DATES COVERED 00-00-1984 to 00-00-1984	
4. TITLE AND SUBTITLE Performance Data of U.S. Naval Observatory VLG-11 Hydrogen Masers Since September 1983				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Naval Observatory, Time Service Department, 3450 Massachusetts Avenue NW, Washington, DC, 20392				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES Proceedings of the Sixteenth Annual Precise Time and Time Interval (PTTI) Applications and Planning Meeting, Greenbelt, MD, 27-29 Nov 1984					
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 10	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified			

TABLE 1

CHRONOLOGY OF VLG-11 MASER ACTIVITY AT U.S.N.O.

13 Sept. 1983	Power to masers turned off at SAO. Masers shipped to the U.S.N.O. by truck.
14 Sept. 1983	Masers arrive at U.S.N.O. Power turned on -- both masers oscillating. P19 degaussed.
22 Sept. 1983	$\Delta f/f$ (P18-UTC USNO) = -1.13×10^{-12} $\Delta f/f$ (P19-UTC USNO) = 0.93×10^{-12} $\Delta f/f$ (P18-P19) = -2×10^{-13} (This, with synthesizer set at 1420405751.68700, which was our best estimate for UTC at SAO via Loran "C". Our probable error in UTC is $\pm 5 \times 10^{-13}$.) Conclusion: Shipment did not alter the cavity frequency significantly.
26 Sept. 1983	Both P18 and P19 were tuned. After tuning $\Delta f/f$ (P19-P18) = 0.11×10^{-13} Maser cavity frequency shift was found to have been as follows: $\Delta f_c(P18) = +40.1 \text{ Hz.}$, $\Delta f_c(P19) = +24.68 \text{ Hz.}$
27 Oct. 1983	$\Delta f/f$ (P19-P18) = 3.03×10^{-13} After tuning P19 $\Delta f/f$ (P19-P18) = 2.08×10^{-13} $\Delta f_c(P19) = +34.55 \text{ Hz.}$
30 Jan. 1984	$\Delta f/f$ (P19-P18) = 3.9×10^{-13} After tuning P18 and P19 $\Delta f/f$ (P19-P18) = 0.8×10^{-13} $\Delta f_c(P18) = +28.9 \text{ Hz.}$, $\Delta f_c(P19) = +59.2 \text{ Hz.}$
27 Feb. 1984	Power off P18 for several hours for installation of U.S.N.O. Master Clock System.
24 Mar. 1984	Power off P19 for several hours for installation of U.S.N.O. Maser Clock System.
10 May 1984	P19 automatically tuned using U.S.N.O. System. $\Delta f_c(P19) = +46.4 \text{ Hz.}$
16 May 1984	$\Delta f/f$ (P19-P18) = -0.6×10^{-13} After tuning P18 $\Delta f/f$ (P19-P18) = $+2.4 \times 10^{-13}$ $\Delta f_c(P18) = +25.4 \text{ Hz.}$

From the drift rate plot shown in Fig. 2, we see that tuning the masers had no apparent effect on the drift rate. From the chronology we see that the cavity resonator frequency of both P18 and P19 required systematic frequency

corrections to lower frequencies. The cavity frequency shifts obtained from the tuning data are shown in Fig. 3. From these data and our knowledge of the line Qs of the masers we can predict an average drift rate of the maser output frequency. For P19 we have 7×10^{-15} per day and for P18 we have 4×10^{-15} per day, between September 1983 and April 1984. This is in reasonably good agreement with drift data in February 1984, when P19 drifts $+9 \times 10^{-15}$ per day and P18 drifts 4×10^{-15} per day. The mistuning rate of the cavity, if ascribed to a change in axial length of the cylindrical cavity, requires a change of length for P18, $\frac{\Delta \ell_{18}}{\Delta T} = -1.9 \times 10^{-8}$ cm/day and for P19, $\frac{\Delta \ell_{19}}{\Delta T} = -3.8 \times 10^{-8}$ cm/day.

To relate this scale of dimensions to something very small, we note that a hydrogen atom has a diameter of about 10^{-8} cm. From the drift behavior and cavity frequency measurements we note the following:

1. The frequency change of the cavity is the dominant effect on the masers' frequency
2. The early drift rate appears more severe than the later drift and the overall drift rate seems to be asymptotically approaching zero.

The properties of ultra stable materials and the behavior of optically contacted surfaces in extremely stable materials have been described by S.F. Jacobs[2] from observations made using an iodine stabilized laser to measure length changes.

Figure 4, reproduced from reference 2, shows the settling of optically contacted surfaces in very high stability materials. The cavity cylinder and end plates of the SAO VLC-11-series masers are made of Cer-Vit C101[®]. After being ground to shape they are stress relieved by being etched in the surface microcracks[3] created in the grinding process. The mating surfaces are then optically polished and the cavities assembled under clean conditions so that

white light fringes are observed over the circumference of the joints between the cylinder and the endplates.

The cavities were assembled in May of 1983, and it is likely that the settling of the end plates was still in progress during late 1983, and early 1984. The settling behavior we observe with the polished surfaces of these cavities is at a much smaller rate than the previously observed settling behavior of cavity joints that were made with surfaces ground to a roughly 16 micro-inch finish. The settling rate was about 1 r.m.s. surface roughness distance in the first 40 days. The present surfaces are at least 10 times smoother and flatter, and the amount of initial mistuning after assembly has been substantially reduced.

The long-term dimensional behavior of structures made of extremely high stability material can be described in terms of $\frac{1}{l} \frac{\Delta l}{\Delta t}$, the "creep rate". Measurements of creep were made by S.F. Jacobs^[2] in terms of optical path changes detected using a stabilized laser. His data give $\frac{1}{l} \frac{\Delta l}{\Delta t} \sim +5 \times 10^{-10}$ per day for Cer-Vit[®] (Cer-Vit C101 - Owens Illinois). Other materials, such as Zerodur[®] (Heraeus-Schott), Ultra Low Expansion Titanium Silicate[®] (Corning), Homosil[®] fused silica (Heraeus-Schott), and Corning[®] 7940 fused silica have creep rates between $+5 \times 10^{-10}$ and -5×10^{-10} per day.

If we ascribe the maser frequency drift of the later months shown in Fig. 2 to cavity mistuning from material creep we obtain a rate of about -3×10^{-10} per day for Cer-Vit.

This agrees in magnitude with Jacobs' measurement on stable materials. It is opposite in sign for his creep rate for Cer-Vit, but agrees with his data for the other materials, which all have negative creep rates. This difference in sign for Cer-Vit may result from variations from sample to sample or from our

700°C cavity silvering process.

The performance of these masers indicates that the long-term stability of today's masers is chiefly governed by properties of the cavity materials. Electronic systems that stabilize the cavity resonance frequency beyond these levels must be capable of maintaining the maser frequency to better than a few parts in 10^{15} per day for long periods of time.

REFERENCES

1. Winkler, G.M.R., "Improved master-clock reference system at the U.S.N.O.," Proc. 15th Ann. Precise Time and Time Interval Planning Meeting, U.S. Naval Research Laboratory, pp 237,-248 (1983).
2. Jacobs, S.F., "Dimensional stability measurements of low thermal expansivity," Proc. 2nd Freq. Standards and Metrology Symp., U.S. National Bureau of Standards, pp. 269-278 (1976).
3. Muffoletto, C. Verne, "Reflective and refractive scattering of ultraviolet radiation caused by state-of-the-art optical grinding and polishing techniques." In Reflecting optics for synchrotron radiation. Soc. Photo-optical Instrumentation Engineers, vol. 315, pp. 85-88 (1981).




FIGURE 1




FIGURE 2




FIGURE 3




FIGURE 4

QUESTIONS AND ANSWERS

JACQUES VANIER, NATIONAL RESEARCH COUNCIL: What was the line Q that you observed in the VLG-11?

MR. MATTISON: The line Q that we used to get was on the order of 1.1 to 1.3 times ten to the ninth. More recently we have been getting values on the order of 1.8 to 1.9 times ten to the ninth.

MR. VANIER: I believe that there is a large gain to be made there. Simply a redesign of the bulb and of the collimator, so that you can increase that by a factor of three or four. Then the drift that you were talking about before, due to the creeping of the cavity, would be diminished dramatically. That would be fantastic.

MR. MATTISON: You are referring to changing the design of the collimator?

MR. VANIER: Yes. Because you can make it for a very long time constant, and it will still work very beautifully, so that you would be limited by the wall then.

MR. MATTISON: I does get limited by the wall. That increase in line Q that you observed has been due to our method of applying the teflon. We haven't changed the design at all.

MR. McCOUBREY: My impression is that with the advances you are making, there is going to be more and more interest in the actual structure and morphology of those surfaces. Maybe some of the polymer scientists would have to play a role in this, because I would expect that whatever happens with this teflon, and how it rearranges itself is something that they have looked into, and probably understand fairly well these days.

MR. MATTISON: Our method of applying teflon has changed. It is essentially a black art. All we know is that there is a recipe, and we apply it according to the recipe, and it works. If we do it a different way, it may work better.

MR. McCOUBREY: It sounds like there are some really interesting possibilities.